



GOOD CATCH DESCRIPTION

Good Catch on Derrick:

Oxygen/Acetylene portable gas cylinder cart was rotted out on bottom, this was just prior to lifting in the air where the bottles could have easily dropped out of the rack.



IMMEDIATE ACTION TAKEN

Oxygen/Acetylene portable gas cylinder cart removed from service along with ordering a new one.

Involved Job Title: Picking up Oxygen/Acetylene bottle rack.

Location: Mississippi River

Alert Type: Injury

Good Catch Date: 10/12/2017

Please review this Safety Alert with your crews and coworkers at your next crew meeting. Discuss similar work exposures and/or conditions at your job site and methods that can be used to prevent a similar incident from occurring.