




GOOD CATCH DESCRIPTION

After a days use, doing the job order, the AB's noticed both safety latches on the hooks were damaged on the come-a-long during the job. The tool had been inspected before beginning as per JSA and and the latches were both good. The tool took some rough use during the work and we felt this was the cause of the failure.



IMMEDIATE ACTION TAKEN

Taken out of service.

Involved Job Title: Remove and Replace

Location: Liberty Island

Alert Type: Injury

Good Catch Date: 03/11/2016

Please review this Safety Alert with your crews and coworkers at your next crew meeting. Discuss similar work exposures and/or conditions at your job site and methods that can be used to prevent a similar incident from occurring.