



## GOOD CATCH DESCRIPTION

A staff member informed the mate that we was going on the spill deck to inspect the drag head. Upon arriving on the spill deck he was stopped by the able bodied seaman (AB) from inspecting the drag head since they did not have on the appropriate PPE.

The employee was not wearing Metatarsal protection which is required to inspect or clean the drag head when debris is identified in the drag head.



## IMMEDIATE ACTION TAKEN

The AB provided the appropriate Metatarsal protection and the employee put on the equipment on prior to inspecting the drag head.



Involved Job Title: Drag Head Inspection

Location: Dredge Padre Island

Alert Type: Injury

Good Catch Date: 01/27/2016

Please review this Safety Alert with your crews and coworkers at your next crew meeting. Discuss similar work exposures and/or conditions at your job site and methods that can be used to prevent a similar incident from occurring.